

Oil Field Environmental Incident Summary

Incident: 20151210132825 **Date/Time of Notice:** 12/10/2015 13:28

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: DIAMOND FEDERAL C 1-31H

Field Name: T. R.

Well File #: 15932

Date Incident: 12/9/2015 **Time Incident:** 15:00

Facility ID Number:

County: BILLINGS

Twp: 141

Rng: 100

Sec: 31

Qtr:

Location Description: Spill was contained inside of the secondary containment dike. This tank battery is located on the Thompson 1-30NH (NDIC #15298) pad.

Submitted By: Todd Senescall

Received By:

Contact Person: Lester Iverson
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	25	Barrels	25	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

location soil

Action Taken or Planned:

Valve replaced, standing liquid sucked up and contaminated soil removed. Exact cause of the valve failure has not yet been determined.

Wastes Disposal Location: Liquid - SWD
Soil - R360

Agencies Involved: Nichole Nelson, NDIC Inspector
Lori Ford, BLM Dickinson

Updates

Date: 12/10/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on the facility site. NDIC retains oversight.